

## Inspection Photos

Location Name: Country 1 29-4

API #: 05-123-26421

Location ID: 310450



Wellhead looking east. Well is TA



Battery looking north



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Country 1 29-4

API #: 05-123-26421

Location ID: 310450



**Unused equipment on west side of tank battery and  
between tank battery and separator**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources