

Inspection Photos  
Location Name: Razor #26J-2633L  
API: 05-123-37495



Photo 1: Location, looking NE



Photo 2: Wellhead, looking NW

Inspection Photos  
Location Name: Razor #26J-2633L  
API: 05-123-37495



Photo from prior inspection for comparison

Photo 2: Wellhead sign for current operator installed, sign for old operator still present

**Inspection Photos**  
**Location Name: Razor #26J-2633L**  
**API: 05-123-37495**



**Photo from prior inspection for comparison**



**Photo 4: Damaged tanks removed.**