

Inspection Photos  
Location Name: South Shale Ridge 10-15  
Location ID: 312612



**Photo 1. Well has been plugged, but had not been cut off and buried at time of inspection.**