



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), dropseed (*Sporobolus* sp.), and fourwing saltbush (*Atriplex canescens*).



Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of what appears to be water catchment in northern portion of the project area.