



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the northern portion of the project area from the northwestern corner facing eastward. Large kochia (*Kochia scoparia*) plants are growing throughout the well pad area, are drying, and will soon become debris that can blow off of the project area.



Photo 3: View of the western portion of the project area from the northwestern corner facing southward. Large kochia plants/debris are evident.



Photo 4: View of the eastern portion of the project area from the northeastern corner facing southward.