

Construction and Stormwater Inspection

September 27, 2017

Operator: 8 NORTH LLC - #10575

Location ID: 443555

Weld County, CO

NENW Section 36 T12N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Silverback /36-A Pad
Location ID: 443555



Photo 1. Photo taken from the entrance of location on CR 136, facing West. Tracking pad not adequately maintained to prevent tracking of material offsite.

Inspection Photos
Location Name: Silverback /36-A Pad
Location ID: 443555



Photo 2. Photo taken from CR 136 east of entrance, facing West. Tracking pad not adequately maintained to prevent tracking of material offsite.

Inspection Photos
Location Name: Silverback /36-A Pad
Location ID: 443555



Photo 3. Photo taken from CR 136 west of entrance, facing West. Tracking pad not adequately maintained to prevent tracking of material offsite.

Inspection Photos
Location Name: Silverback /36-A Pad
Location ID: 443555



Photo 4. Photo taken from the entrance of location, facing South. Photo illustrates tracking pad not adequately maintained to prevent tracking of material offsite.