

Inspection Photos

9/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 405904

Inspection Doc. Number: 682502615

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 405904



Photo 1: Photo taken from the east end of the battery location. Inspection doc. #675103849 and #682502113 required operator to remove riser by 6/30/2017. Corrective action remains applicable.



Photo 2: Photo taken from the access road facing north. Inspection doc. #682502113 required operator to reclaim road and location by 11/15/2017. This corrective action remains applicable.