

# Inspection Photos

9/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327240

Inspection Doc. Number: 682502621

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327240



**Photo 1:** Photo taken from the west end of the battery location, facing northwest. Inspection doc. #682502147 and #675103862 required operator to remove riser at the battery in accordance to 1004.a reclamation requirements. Photo shows riser has not been removed.



**Photo 2:** Photo taken from the east end of the battery location within the tank berm. Photo shows pipe riser that has been tagged and painted per the 2017 Flowline NTO, but has not been removed per the NTO required dates. This riser will need to be removed per the NTO and per 1004.a reclamation rules.