

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2017

Submitted Date:

10/02/2017

Document Number:

687900486

FIELD INSPECTION FORM

Loc ID 312074 Inspector Name: DURAN, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 600 E EXCHANGE AVE
City: FORTH WORTH State: TX Zip: 76164

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------------|---|
| Fitzgerald, Edie | 719-845-2108/719-859-1394 | Edie_Fitzgerald@xtoenergy.com | Env. Tech, Raton Basin |
| Trujillo, Irwin | 719-846-0272/719-859-2264 | irwin_trujillo@xtoenergy.com | Sr. Env. Tech., Raton Basin |
| Harrison, Lyndon | 505-333-3100 | Lyndon_Harrison@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 259211 | WELL | PR | 09/23/2003 | GW | 071-07205 | APACHE CANYON 19-10V | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---------------|-------|--|
| | Type WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | | | corrective date |
|--------------------------|-----|-------|--|--|-----------------|
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Deadman # & Marked | # 4 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Vertical Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Progressive Cavity | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 259211 Type: WELL API Number: 071-07205 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--------------|--------|------------|
| Rain drizzle | duranj | 10/02/2017 |