

- Thomas Jacquez G 1
- 05-067-07722



Photo 1: Wellhead sign.

- Thomas Jacquez G 1
- 05-067-07722



Photo 2: Unused 1" riser at wellhead.

- Thomas Jacquez G 1
- 05-067-07722



Photo 3: Erosion channels and rilling in backside tank berm..

- Thomas Jacquez G 1
- 05-067-07722



Photo 4: Sediment deposited inside tank battery bermed area.

- Thomas Jacquez G 1
- 05-067-07722



Photo 5: Sediment deposits around tank heaters.

- Thomas Jacquez G 1
- 05-067-07722



Photo 6: Erosion channel in cut slope and sediment plume on location.