

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2017

Submitted Date:

10/03/2017

Document Number:

666803785

**FIELD INSPECTION FORM**

Loc ID 383334 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		COGCC.inspections@caerus oilandgas.com	<a href="#">All Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301914	WELL	PR	07/28/2010	GW	045-18322	GMU 22-11B (K22NW)	TA
301915	WELL	PR	08/07/2010	GW	045-18323	GMU FEE 22-14A (K22NW)	PR
301916	WELL	PR	06/14/2011	GW	045-18324	GMU 22-11 (K22NW)	PR
301917	WELL	PR	08/04/2010	GW	045-18325	GMU FEE 22-14 (K22NW)	PR
301918	WELL	PR	08/01/2010	GW	045-18326	GMU 22-6(K22NW)	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: [flow lines](#)

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 5

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator # 5

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 0

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment: [Centralized battery](#)

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		39.508468,-107.762338
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>			
Facility ID: <u>301914</u>	Type: <u>WELL</u>	API Number: <u>045-18322</u>	Status: <u>PR</u> Insp. Status: <u>TA</u>
<b>Producing Well</b>			
Comment: <u>Plunger lift</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
<b>Workover</b>			
Comment: <u>Work over rig on well, testing tubing</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>301915</u>	Type: <u>WELL</u>	API Number: <u>045-18323</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <u>Plunger lift</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>301916</u>	Type: <u>WELL</u>	API Number: <u>045-18324</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <u>Plunger lift</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>301917</u>	Type: <u>WELL</u>	API Number: <u>045-18325</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <u>Plunger lift</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>301918</u>	Type: <u>WELL</u>	API Number: <u>045-18326</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <u>Plunger lift</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
Seeding	Pass					
		Culverts	Pass			
Gravel	Pass					
Sediment Traps	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT