

Photo#1:
Overview of Location to West



September 27, 2017

Photo#2:

Heavy infestation of Thistle throughout Location.



September 27, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gulfport PA West Danforth API#081-07412

Photo#3:
Livestock Watering facility at South edge of Location



September 27, 2017

Photo#4:
Access Road is Not Reclaimed.



Photo#5:

Areas of Pad are Graveled ; other areas remain compacted & revegetating with Weedy species.

Photo#6:



September 27, 2017

Photo#7:

1st Year Plants / Rosettes of Thistle & Houndstongue emerged across pad & Slope areas



Photo#8:



September 27, 2017

Photo#9:

View of Drainage area at North side of Pad; dark brown vegetation is Thistle .



September 27, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gulfport PA West Danforth API#081-07412

Photo#10:

View of Reference Area Vegetation to North East of Location.



September 27, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gulfport PA West Danforth API#081-07412