



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with blue grama (*Bouteloua gracilis*), western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and fourwing saltbush (*Atriplex canescens*).



Photo 3: View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4: View of silt trap in the southwestern portion of the project area, appears to be functioning.



Photo 5: View wood debris in the northwestern portion of the project area. Weeds have recently been controlled.