

Final Reclamation Inspection

October 4, 2017

Operator: WELLINGTON OPERATING COMPANY - 95233

API: 05-069-05284

Larimer County, CO

NESW Section 7 T9N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: WELLINGTON MUDDY UNIT #25-1

API: 05-069-05284



Photo 1. Photo taken from the northern well location, facing South. Gravel pile has been removed but gravel remains at the well location, and appears location was mowed, including noxious weeds. Appears the well marker and pipe riser have been removed.

Photo 2. Photo taken from the approximate center of the location, facing West. Refer to Photo 1 for description of observations.