

Inspection Photos

Location Name: Meyring 13-27 flowline release

Facility ID: 452298

SW¼ SW¼ Section 27 Township 7 North Range 65 West



Photo 1: Excavation at flowline release discovery point on west side on Lone Tree Creek. Viewing southwest



Photo 2: Excavation at secondary excavation on east side of Lone Tree Creek. Viewing south



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Meyring 13-27 flowline release
Facility ID: 452298
SW¼ SW¼ Section 27 Township 7 N



Photo 3: View of Lone Tree Creek looking west toward excavation at primary release point.



Photo 4: Viewing upstream (north) on Lone Tree Creek.



Inspection Photos

Location Name: Meyring 13-27 flowline release

Facility ID: 452298

SW¼ SW¼ Section 27 Township 7 North Range 65 West



Photo 5: Excavation on east side of Lone Tree Creek viewing west toward primary excavation.



Photo 6: Flowline of Meyring 13-27 disconnected at separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources