

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2017

Submitted Date:

09/29/2017

Document Number:

690300062

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Spencer, Stan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10128  
 Name of Operator: BARGATH LLC  
 Address: 2717 COUNTY ROAD 215 SUITE 200  
 City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 1 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
Garrigues, Annette	970 285-5946	annette.garrigues@williams.com	

**General Comment:**

**Environmental**

**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: \_\_\_\_\_

Comment: Site meeting to discuss ongoing REM 7646 at Jangles Compressor Station. Meet with Annette Garrigues (Williams), Craig Tysee (Chevron), Phil Osborne (consultant w Aptim) and GDI Drilling (Dean and Eric.). Meeting is to to confirm drilling locations for expanded site investigation under REM 7646. Purpose is to establish 2 new POC wells, further define plume and assess current conditions at source area. Drilling delayed by difficult subsurface conditions for both potholing and drilling. All wells ultimately completed by 9/25.

Corrective Action: Submit supplemental F-27 with analytical results for soil and groundwater samples. Provide any proposed changes to remediation plan prior to implementation.

Date: 11/30/2017

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401417123	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263375">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263375</a>
690300063	Potholing for monitoring well at Jangles CS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263371">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263371</a>