

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Well needs to added to location 335107

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Location photo

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Separators and battery sign

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Tank battery

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Sediment filled ditch and packed culvert

GV 17-32
Api# 05-045-06629
Inspection # 689700410



Sediment filled ditch and packed culvert