

Inspection Photos



Photo 1. 2015 aerial image of the access road and location.

Inspection Photos



Photo 2. Beginning of the access road facing south.

Inspection Photos



Photo 3. Facing southeast along the access road. There is predominately undesirable weeds (Kochia) growing along the road. There is no gravel present along the road.

Inspection Photos



Photo 4. Facing southeast along the access road. The area along the side of the road contains undesirable weeds and is not adequately stabilized with desirable vegetation.

Inspection Photos



Photo 5. There are signs of stormwater erosion occurring along the road.

Inspection Photos



Photo 6. Facing southwest along the access road. There is stormwater held back by the road on the eastern side. There is a potential for stormwater to flow across the road causing erosion however there was minimal signs of this occurrence.

Inspection Photos



Photo 7. Facing southwest along the access road where it gradually ascends. There is erosion occurring down the slope of the road.

Inspection Photos



Photo 8. Facing southeast where access road turn toward the location. There is erosion occurring down the slope of the road.

Inspection Photos



Photo 9. West side of the location facing east.

Inspection Photos



Photo 10. Northwest corner of the pad fill slope facing east.

Inspection Photos



Photo 11. Facing east toward the northern portion of the location. There is predominately undesirable weeds (Kochia) growing in this area.

Inspection Photos



Photo 12. View of ground cover at the northwestern side of the location. There is predominately undesirable weeds (Kochia) growing in this area.

Inspection Photos



Photo 13. East side of the location facing west.

Inspection Photos



Photo 14. East side of the location facing northwest. There is a hunting blind set up at the northeast corner.

Inspection Photos



Photo 15. Facing east along the south cut slope side of the location.

Inspection Photos



Photo 16. South side of the location facing northeast.