


Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



CE&P Facility ID: 287848

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



One of six monitoring wells.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



Material stocked piled on Location.



Storm water detention pond located in the western boundary of the Facility



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



Storm water detention pond, looking north.



Looking east across the Location from the storm water detention pond.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



Former treatment cell (looking east from storm water detention pond).



Looking northwest from storm water detention pond.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



Former treatment cell, looking east from storm water detention pond.



Monitoring well located in NW corner of the facility (looking North).



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc (#10120)

Facility ID: 287848



Looking south toward storm water detention pond.



Looking south to southeast across the Facility.

