

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 326853

Inspection Doc. Number: 682502653

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326853



Photo 1: Photo taken from the access road. Photo shows corn crop vegetation is visibly stunted when compared to the adjacent reference area (see photo 2). Unable to find evidence that additional reclamation activities have been conducted per the corrective actions. 6 foot measuring stick for reference.



Photo 2: Photo taken from the adjacent reference area. Photo shows crop height in the reference area exceeds 6 feet. 6 foot measuring stick for reference.