

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 447546

Inspection Doc. Number: 682502655

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the western portion of the battery facility, facing south. Photo shows pipe riser equipment that appears to be abandoned. Riser needs to be removed in accordance to COGCC rule 1004.a