

# Inspection Photos

10/05/2017

Operator: PDC ENERGY INC - 69175

Location ID: 407785

Inspection Doc. Number: 682502657

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 407785



**Photo 1:** Photo taken from the south end of the well location, facing northeast. Photo shows crop has been harvested, however unable to find evidence that additional reclamation work (such as compaction alleviation) has been performed.



**Photo 2:** Photo taken from the south end of the well location, facing northwest. Photo shows crop has been harvested, however unable to find evidence that additional reclamation work (such as compaction alleviation) has been performed.