

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 322834

Inspection Doc. Number: 682502659

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 322834



Photo 1: Photo taken from the northwest end of the former battery facility, facing southeast. Photo shows areas appear to have been re-seeded and stabilized via crimped straw.



Photo 2: Photo taken from the northwest end of the former battery facility, facing south. Photo shows areas appear to have been re-seeded and stabilized via crimped straw.



Photo 3: Photo taken from the east end of the former battery location, facing west. Photo shows access road appears to have been re-seeded and stabilized via crimped straw.



Photo 4: Photo taken north of the well location, facing south. Photo shows well and access road appears to have been reseeded and stabilized via crimped straw. Photo also shows areas of the access road where the ruts remain visible, this suggests the required compaction alleviation may not have been performed per reclamation rules. Reclamation will not pass until the required compaction alleviation of the access road and well have been performed.



Photo 5: Photo taken north of the well location, facing west. Photo shows meter shed equipment has not been removed.



Photo 6: Photo taken from the meter shed, north of the well. Photo shows equipment has been removed from inside the meter shed.