

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327040

Inspection Doc. Number: 682502661

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the former battery location. Photo shows areas crop that have not achieved uniform establishment, and remains visibly stunted when compared to the reference area (photo 2). Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 2: Photo taken from the adjacent reference area. Photo shows crop growth in the reference appears to exceed 6 feet in height. 6 foot measuring stick for reference.