

Inspection Photos

10/05/2017

Operator: PDC ENERGY INC - 69175

Location ID: 332234

Inspection Doc. Number: 682502663

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the former battery location, facing southwest. Photo shows additional reclamation and revegetation activities do not appear to have been conducted.



Photo 2: Photo taken from former battery location, where the meter shed had resided. Photo shows gravel does not appear to have been removed.



Photo 3: Photo taken from the adjacent reference area. Photo shows perennial alfalfa crop on reference.