

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 318970

Inspection Doc. Number: 682502666

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the former battery location, facing south. Photo shows crop has not achieved uniform vegetative cover. Unable to find evidence that additional reclamation activities have been conducted per the corrective actions.



Photo 2: Photo taken from the north end of the former battery location, facing west. Photo shows crop appears to have been harvested, however, unable to find evidence that additional reclamation activities have been conducted per the corrective actions.