

# Inspection Photos

10/05/2017

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 329578

Inspection Doc. Number: 682502670

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC - 10459  
Location ID: 329578



**Photo 1:** Photo taken from the former well, facing north. Photo shows riser identified in the previous inspection has been removed per the corrective action. Location still requiring reclamation including re-contouring/re-grading and revegetation.