

# Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 332748

Inspection Doc. Number: 682502676

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the northwest end of the battery location, facing south. Photo shows four (4) pipe risers that were required to be removed still remain.