

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



00284586

C

| | | | |
|---|------------------|---|---|
| <input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| API No. 05- 075 - 9258 | | LEASE NAME: N. Minto I #6 | |
| LOCATION: NENE 26-9N-53 | | OPERATOR: Pease | |
| DATE: 1-16-95 | | INSPECTOR: Brinkley | |
| Insp. Type: Pr | Insp. Status: Pr | PA: Y N | Pass/Fail: P <input checked="" type="radio"/> F |
| | | Viol: Y <input checked="" type="radio"/> N | NOV: Y N |

| INSPECTION ITEM | COMMENTS | INPUT |
|---|---|-------|
| Well ID Signs (Rule 210) | Update and install signs | |
| Pits (Reserve/Production) (Rule 902, 903, 904) | pit 5 km 20 ² water injection, pit 200 ² | |
| Fences (Rule 604.C.(3), 1003.A) | | |
| Tank Battery Equipment (Rule 604) | Bad NENE 25-9N-53W 5 km tank, 2-300, VT, | |
| Fire Walls/Berms/Dikes (Rule 604) | OK | |
| General Housekeeping (Rule 603.G) | OK | |
| Spills (Oil/Water) (Rule 908) | oil in pit (5 km) | |
| Bradenhead (Rule 207) | | |
| Drilling Well/Workover (Rule 315) | | |
| Surface Rehabilitation (Rule 317) | | |
| Miscellaneous | WI - 500 psi | |

| | |
|---|----------------|
| CORRECTIVE ACTION REQUIRED: Removal oil from pit or install pit cover. Install well signs. | |
| Date Corrective Action Required By: 3-28-96 | Date Remedied: |

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

Notified when pit is clean before 3-28-96.

White - File Green - Operator Canary - Well Site