

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303) 894-2100	
API No. 05- 075 - 9258		LEASE NAME: N. Minto I #6	
LOCATION: NENE 26-9N-53		OPERATOR: Pease	
DATE: 1-16-95		INSPECTOR: Brinkley	
Insp. Type: Pr	Insp. Status: Pr	PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/> Viol: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	Update and install signs	done
Pits (Reserve/Production) (Rule 902, 903, 904)	pit 5 km 202 water injection pit 2002	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	Bad NENE 25-9N-53W 5 km tank, 2-300, VT,	
Fire Walls/Berms/Dikes (Rule 604)	OK	
General Housekeeping (Rule 603.G)	OK	
Spills (Oil/Water) (Rule 908)	oil in pit (5 km)	
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	WI - 500 psi Battery rebuilt Install Water tanks done 6/21/96	
CORRECTIVE ACTION REQUIRED: Removal oil from pit or install pit cover. Install well signs. Date Corrective Action Required By: 3-28-96 Date Remedied:		

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

Notify Ed when pit is clean before 3-28-96.
 Everything has been chg. and cleaned up 2/16