

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 1: Wellhead sign.

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 2: Unused 1" riser at wellhead.

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 3: Domestic Tap.

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 4: (3) unused 1" risers at wellhead.

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 5: Installed straw waddles for new drill.

- Crigler - MVRD Unit 1
- 05-067-05377



Photo 6: Unused section of pipe along fencing.