

Photo#1:

View over Location Center to North.



September 26, 2017

Photo#2:

View over Location Center to South.



September 26, 2017

Photo#3:

View over Location Center to East.



September 26, 2017

Photo#4:

View over Location Center to West.



September 26, 2017

Photo#5:

Photo#6:

Close ups of Ground Conditions; a few pieces of Debris noted on Location



September 26, 2017