

Inspection Photos  
Location Name: Della Griffith 1  
API: 05-067-05264  
Inspection Number:685200402



**Weeds/vegetation inside containment berms 8.17.17  
inspection**



**Corrective actions not adequately performed 10.4.17  
inspection**

Inspection Photos  
Location Name: Della Griffith 1  
API: 05-067-05264  
Inspection Number:685200402



**Combustible material around fired equipment 8.17.17 inspection photo**



**Corrective action not performed or conditions re-occurred 10.4.17 inspection photo**



Inspection Photos  
Location Name: Della Griffith 1  
API: 05-067-05264  
Inspection Number: 685200402



**Well sign with invalid operator 24-hour contact number**