

Inspection Photos

10/18/2017

Operator: DJ RESOURCES INC - 10213

Location ID: 390645

Inspection Doc. Number: 682502712

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: DJ RESOURCES INC - 10213
Location ID: 390645



Photo 1: Photo taken from the northwest end of the location, facing southeast. Photo shows location remains predominantly exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



Photo 2: Photo taken from the east end of the location, facing west. Photo shows location remains predominantly exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



Photo 3: Photo taken from the location. Photo shows location remains predominantly exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



Photo 4: Photo taken from the adjacent reference area. Photo shows vegetation over the reference area.