

Inspection Photos

10/18/2017

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312291

Inspection Doc. Number: 682502716
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 1: Photo taken from the west end of the location. Photo shows erosion degradation. Previous inspection required operator to implement temporary stabilization controls. Photo shows no BMPs have been installed.



Photo 2: Photo taken from the northwest end of the pit. Photo shows erosion degradation. Previous inspection required operator to implement temporary stabilization controls. Photo shows no BMPs have been installed.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 3: Photo taken from the southwest end of the pit, facing east. Photo shows no BMPs have been installed.



Photo 4: Photo taken from the south end of the pit, facing east. Photo shows no BMPs have been installed.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 5: Photo taken from the southeast end of the pit, facing northwest. Photo shows no BMPs have been installed.



Photo 6: Photo taken from the east end of the pit, facing west. Photo shows no BMPs have been installed.



Photo 7: Photo taken from the northeast end of the pit, facing west. Photo shows no BMPs have been installed.