

# Final Reclamation and Stormwater Inspection

October 20, 2017

Operator: LILIS ENERGY INC- #10495

API: 05-039-06608

Elbert County, CO

SWSE Section 10 T6S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 1.** Photo taken on October 20, 2017 from the southern location, facing West. Photo illustrates no further reclamation activities have been conducted since the previous inspection on September 7, 2017.



**Photo 2.** Photo taken on September 7, 2017 from the same location and direction as Photo 1.

Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 3.** Photo taken on October 20, 2017 from the western location, facing South. Photo illustrates no further reclamation activities have been conducted since the previous inspection on September 7, 2017.



**Photo 4.** Photo taken on September 7, 2017 from the same location and direction as Photo 3.



Inspection Photos  
Location Name: COGGINS #10-34  
API: 05-039-06608



**Photo 5.** Photo taken from the southeastern location, facing South. BMP maintenance needed along a section of the silt fence. Photo illustrates no further work has been conducted as of October 20, 2017.



**Photo 6.** Photo taken on September 7, 2017 from the same location and direction as Photo 5.