

- Ester 1 / 05-067-06232



Photo 1: Oily residue remaining in pit.

- Ester 1 / 05-067-06232



Photo 2: Pit fencing.

- Ester 1 / 05-067-06232



Photo 3: Wellhead and flowline. Debris around wellhead.

- Ester 1 / 05-067-06232



Photo 4: Control box and debris.

- Ester 1 / 05-067-06232



Photo 5: Debris.

- Ester 1 / 05-067-06232



Photo 6: Power pole and line.

- Ester 1 / 05-067-06232



Photo 7: Unmarked anchor.

- Ester 1 / 05-067-06232



Photo 8: Access road looking E towards location.

- Ester 1 / 05-067-06232



Photo 9: Access road looking E back towards location closer to field.

- Ester 1 / 05-067-06232



Photo 10: Farm two track road. Old access road to location is to the right of power pole.