

Inspection Photos

Location Name: Ziggy USX AB 19-99HZ

API #: 05-123-31474

Location ID: 416737



Wellhead looking east, stained soil around wellhead



Battery looking south. Unused fencing on the ground northeast edge of location. Needs picked up

