



Photo 1. View of the project area from the northeastern edge of the working area facing center.





Photo 2. View of the northern portion of the project area from the northeastern edge facing westward. Tanks are being stored within the northern portion of the project area.





Photo 3. View of the southern portion of the project area from the southeastern corner of the working area facing westward. Vegetation is becoming established on the fill slopes, and largely comprised of western wheatgrass (*Pascopyrum smithii*), blue grama (*Bouteloua gracilis*) and squirreltail (*Elymus elymoides*). Tanks and stockpiled material is stored in the southwestern portion of the project area.



Photo 4. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 5. View of Canada thistles (*Cirsium arvense*) that appear to have been treated within the eastern portion of the project area.



Photo 6. View of sawdust pile in the southwestern corner of the working area.