

Inspection Photos

10/23/2017

Operator: BROWN OIL & GAS LLC - 11001

Location ID: 430981

Inspection Doc. Number: 682502723

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BROWN OIL & GAS LLC - 11001
Location ID: 430981



Photo 1: Photo taken from the west end of the location, facing south. Photo shows vegetation over the reclamation area. Location remains predominantly bare and exposed soil. Unable to find evidence showing additional reclamation activities have been conducted per corrective actions. Vegetation/location is not progressing towards reclamation requirements.



Photo 2: Photo taken from the west end of the location, facing east. See comments under photo 1.

Inspection Photos
Operator: BROWN OIL & GAS LLC - 11001
Location ID: 430981



Photo 3: Photo taken from the west end of the location, facing north. See comments under photo 1.



Photo 4: Photo taken from the center of the location. Photo shows vegetation over the reclamation area to compare to the reference area (see photo 5). Location remains predominantly bare and exposed soil. Unable to find evidence showing additional reclamation activities have been conducted per corrective actions. Vegetation/location is not progressing towards reclamation requirements. 6 foot measuring stick for reference.



Photo 5: Photo taken from the adjacent reference area. Photo shows vegetation on the reference area. Vegetation seen here predominantly Sand Dropseed, Blue gramma, Western wheatgrass, Fourwing Saltbrush, etc... 6 foot measuring stick for reference.