

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2017

Submitted Date:

10/24/2017

Document Number:

680704894**FIELD INSPECTION FORM**

Loc ID 423797 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@srcenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423798	WELL	SI	04/01/2017	OW	123-33731	LOEWEN 22-32D	SI
423800	WELL	SI	06/01/2017	OW	123-33733	LOEWEN 11-32D	SI
423805	WELL	SI	04/01/2017	OW	123-33738	LOEWEN 21-32D	SI
423811	WELL	SI	06/01/2017	OW	123-33742	LOEWEN 25-32	SI
423812	WELL	SI	06/01/2017	OW	123-33743	LOEWEN 12-32D	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vault capacity placard has faded and is illegible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	12/25/2017
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 5		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Multiple tube meter run		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	PBV FIBERGLASS		40.273560,-105.029950
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	300 BBLS	STEEL AST		40.273560,-105.029950
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 423798 Type: WELL API Number: 123-33731 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Facility ID: 423800 Type: WELL API Number: 123-33733 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Facility ID: 423805 Type: WELL API Number: 123-33738 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Facility ID: 423811 Type: WELL API Number: 123-33742 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Facility ID: 423812 Type: WELL API Number: 123-33743 Status: SI Insp. Status: SI

<u>Idle Well</u>		
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

<u>BradenHead</u>		
Comment:	<input type="text" value="Bradenhead valve is exposed at surface."/>	
Corrective Action:	<input type="text"/>	Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	Wells are currently SI
Pilot: OFF	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680704895	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4283204