

## Inspection Photos

Location Name: Steve J 18-10

API #: 05-123-23650

Location ID: 333001



**Wellheads looking west**



**Battery looking northwest**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Steve J 18-10

API #: 05-123-23650

Location ID: 333001



**2-unused/disconnected gas meter runs west of separator, need to be removed**



**Location is washing out on east side of location, discharging sediment off of location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources