

Inspection Photos
Location Name: Moore 13-35
API #: 05-123-19455
Location ID: 330681



Wellhead looking south



1" unused/unmarked steel riser at wellhead

Inspection Photos

Location Name: Moore 13-35

API #: 05-123-19455

Location ID: 330681



Tank battery looking west



Northeast edge of location is washing out

