

Inspection Photos

10/23/2017

Operator: BRITISH AMERICAN OIL PROD CO -
10558 / Chevron USA INC - Operator #16700

Location ID: 389108

Inspection Doc. Number: 682502747

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 289109



Photo 1: Current aerial imager (2015) showing well location and the former battery location. Area marked "photos 3-10" is where pipe risers and various debris was first observed. Red polygon represents area of the former batter and areas where degradation is evident either due to improper reclamation or stormwater runoff onto adjacent lands. Debris was observed scattered throughout this area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Doc. Number: 682502747

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 389108



Photo 2: Photo taken from the well location, facing west. Photo shows pipe riser remaining at well site. Photo also shows areas of the well where vegetation has failed to re-establish.



Photo 3: Photo taken from the well location, facing east. Photo shows pipe riser remaining at well site. Photo also shows areas of the well where vegetation has failed to re-establish.

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 389108



Photo 4: Photo taken from the north end of the former battery location, facing south. Photo shows various pipe risers and debris that was never removed. Photo also shows areas of the well where vegetation has failed to re-establish.



Photo 5: Photo shows various pipe risers and debris still remaining at former battery.



Photo 6: Photo of sign found within an oil barrel still remaining at the former battery. Sign appears to say "British American Producing CO."

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 389108



Photo 7: Photo of pipe remaining at the former battery location.



Photo 8: Photo of pipe remaining at the former battery location.

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 389108



Photo 9: Photo of pipe and various debris remaining at the former battery location.



Photo 10: Photo of pipe and various debris remaining at the former battery location.

Inspection Photos

Operator: BRITISH AMERICAN OIL PROD CO - 10558 / Chevron USA INC -

Operator #16700

Location ID: 389108



Photo 11: Photo of pipe and various debris remaining at the former battery location.



Photo 12: Photo of pipe and various debris remaining at the former battery location.



Photo 13: Photo taken from the west of the former battery (~40.96787/-103.42702). Photo shows pipe sticking out of ground.