

- Cundiff Federal B 1
- 05-067-07174



Photo 1: Wellhead sign.

- Cundiff Federal B 1
- 05-067-07174



Photo 2: Gravel and soil pile.

- Cundiff Federal B 1
- 05-067-07174



Photo 3: Erosion rilling with sediment flow onto location in NE corner.

- Cundiff Federal B 1
- 05-067-07174



Photo 4: Erosion with sediment flow onto location in NE corner.

- Cundiff Federal B 1
- 05-067-07174



Photo 5: Backhoe bucket and wood on perimeter.

- Cundiff Federal B 1
- 05-067-07174



Photo 6: Rail road tie and concrete block on perimeter.

- Cundiff Federal B 1
- 05-067-07174



Photo 7: Disconnected piping on perimeter.

- Cundiff Federal B 1
- 05-067-07174



Photo 8: Erosion channel on S side of location.

- Cundiff Federal B 1
- 05-067-07174



Photo 9: Wire rope coming out of the ground outside of wellhead fencing.

- Cundiff Federal B 1
- 05-067-07174



Photo 10: Concrete chunks in SW corner of location.