

Inspection Photos
Location Name: Shable #3-32
API: 05-123-26848



Photo 1: Wellhead, looking S



Photo 2: Stained soil at wellhead

Inspection Photos
Location Name: Shable #3-32
API: 05-123-26848



Photo 3: Stained soil at exhaust



Photo 4: Stained soil in engine house