

Puckett 238-25
Api# 05-045-08214
Inspection # 689700540



Location photo

Puckett 238-25
Api# 05-045-08214
Inspection # 689700540



2" elbow connection off edge of location.

Puckett 238-25
Api# 05-045-08214
Inspection # 689700540



2" elbow connection off edge of location.