



**Photo 1. View from the northeastern corner of the project area facing center.**





**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*), brome grass (*Bromus* sp.), and sagebrush (*Artemisia tridentata*).**







**Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.**







**Photo 4. View of pipes and other equipment near the wellhead that do not appear to be in use.**