

# Interim Reclamation and Stormwater Inspection

October 25, 2017

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 427157

Weld County, CO

NENE Section 4 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: Rancho Water Valley Pad /41-4**  
**Location ID: 427157**



**Photo 1.** Photo taken from the north stockpile located on the middle tier, facing Northwest. Northwestern area appears to have been re-graded to direct stormwater flows east towards the sediment basin.



**Photo 2.** Photo taken from the north stockpile located on the middle tier, facing Northeast. Stormwater construction work in process along the northern location.

**Inspection Photos**  
**Location Name: Rancho Water Valley Pad /41-4**  
**Location ID: 427157**



**Photo 3.** Photo taken from the north stockpile located on the middle tier, facing East. Material from the sediment basin is being spread onto the north stockpile and other stormwater erosion areas.



**Photo 4.** Photo taken from the north stockpile located on the middle tier, facing West. Stormwater construction work in process along the western location. Appears a berm is being constructed and the western access road has been removed.