

**Inspection Photos**  
**Location Name: McIntyre Flowback Pits #3 and #4**  
**Facility ID #421066**



**Pipe joints and other unused equipment stored on the western edge of the location.**



**Junk and unused equipment stored along the western edge of the location.**

**Inspection Photos**  
**Location Name: McIntyre Flowback Pits #3 and #4**  
**Facility ID #421066**



**Pit #418791**



**Monitoring well down gradient of pit #418791.**

**Inspection Photos**  
**Location Name: McIntyre Flowback Pits #3 and #4**  
**Facility ID #421066**



**Unused equipment near pit #418791.**



**Discharge into pit #418790.**

**Inspection Photos**  
**Location Name: McIntyre Flowback Pits #3 and #4**  
**Facility ID #421066**



**Gauge stick in pit #418790.**



**Water transfer line and pit #418790.**

**Inspection Photos**  
**Location Name: McIntyre Flowback Pits #3 and #4**  
**Facility ID #421066**



**Pit Facility ID #418791.**



**Pipe line valve can and water transfer line.**